

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,411,986 B2
APPLICATION NO. : 10/808952
DATED : August 12, 2008
INVENTOR(S) : Diaz

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4

Line 63, change "capacitor 393," to --capacitor 392,--

Column 6


Line 66, change "I_{MOD} for C_{OUT} results" to --½ I_{MOD} for C_{OUT} results--

Column 8

Line 3, change "½ I_{MOD} Inductor 460" to --½ I_{MOD}. Inductor 460--

Signed and Sealed this

Seventh Day of September, 2010



David J. Kappos
Director of the United States Patent and Trademark Office